REPORT OF CASING RUN IN HOLE

Well Name & No. GLASS BUTTE ST #1 Date 11-10-81

Driller's TD 1996' E-Log TD _____ Hole Size 6 ¼"

(Indicate top of casing from RKB AFTER cut-off)

RKB- 0 0

DF (or) RT - _____

Ground Level _____



Run bottom to top:(less threads measurements)
(Include float equipment, stage collar, etc.)

Jts.	Description	Footage LT
	LESS: CUT-OFF PIECE	
	TOTAL	
	PLUS: TOP OF CSNG TO RKB	
	Casing set at	

Scratchers @ _____

Centralizers @ _____

REMARKS: TUBING WAS STUCK AT 1200' TO 1200' WORKED FREE - RECOVERED ALL TUBING.

CEMENTING

1st Stage

Kind PORTLAND POZ Slurry

Cement NEAT Amt 22 SKS Wt. 5-1

Additives NONE

Time Start Completed

Mixing N/A Mixing N/A

Pumped A.M.

Plug to W/ psi at P.M.

Returns 100%

Cementing Co JACKSON BROS. OIL CO.

REMARKS N/A

2nd Stage

Kind Slurry

Cement Amt Wt.

Opened Stage Collar W/ psi. Circulation

Time Start Completed

Mixing Mixing

Pumped A.M.

Plug to W/ psi at P.M.

Returns

Job Completed at GLASS BUTTE ST #1

GLASS BUTTE, OREGON

LAKE COUNTY, OREGON

Signed Bill Whitty