

FILE NO. \_\_\_\_\_  
 COMPANY: RECO OIL & GAS COMPANY  
 WELL: CC 44-27-65  
 FIELD: MISTI  
 COUNTY: COLUMBIA STATE OR: \_\_\_\_\_

LOCATION: 3 1/2" FELL & 4 1/2" FSL OF SE CORNER OF  
 SEC27 T14P1N RGE35N  
 OTHER SERVICES: DIF, RC/GR

PERFORMED BY: G. \_\_\_\_\_  
 LOSSING MEASURED FROM: KB 10' FT. ABOVE P.O.  
 DRILLING MEASURED FROM: KB 980.5' D. 980.5'

DATE: 7/4/88  
 RUN: 158943  
 SERVICE ORDER: 2190  
 DEPTH-DRILLER: 2127  
 DEPTH-LOOKER: 2125  
 TOP-LOOKED INTERNAL: 454'  
 CASING - DRILLER: 9.50"  
 CASING - LOOKER: 454'  
 BIT SIZE: 8.5"  
 TYPE FLUID IN HOLE: EZ MUD  
 DENSITY / VISCOSITY: 10.0 / 5.0  
 PH / FLUID LOSS: \_\_\_\_\_  
 SOURCE OF SAMPLE: FLO LINE  
 RHF AT MENS. TEMP.: 2.69 @ 83 F  
 RHC AT MENS. TEMP.: 3.32 @ 83 F  
 SOURCE OF RHF / RHC: MENS @ 1 MENS @ 1  
 TIME SINCE CIRCULATION: 4 HRS @ 188 F  
 HEX. REC. TEMP. DEG. F: 188 F  
 EQUIP. NO. / LOC.: H. 6466 / SEC  
 RECORDED BY: B. KUCH  
 INTERSEED BY: HR. AYDINISKI, JIKSSON

IN MAKING INTERPRETATIONS OF LOGS, OUR EMPLOYEES WILL GIVE CUSTOMER THE BEST FIT OF THEIR BEST JUDGMENT BUT SINCE ALL INTERPRETATIONS ARE OPINIONS BASED ON INTERFERENCES FROM ELECTRICITY OR OTHER DEVIATIONS, WE CANNOT AND WE DO NOT GUARANTEE THE ACCURACY OR CORRECTNESS OF ANY INTERPRETATION. WE SHALL NOT BE LIABLE OR RESPONSIBLE FOR ANY LOSS, COST, DAMAGES OR EXPENSES WHATSOEVER INCURRED OR SUSTAINED BY THE CUSTOMER RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR EMPLOYEES.



REMARKS: RUN ( 1 )  
 CORR SCALES OF -.25, .25 RUN AT CUSTOMER REQUEST  
 BHV COMPUTED FOR 3.5" CSG

**EQUIPMENT DATA**

RUN	TRIP	TOOL	SERIAL NO.	SERIES NO.	POSITION
1	1	CDL	57833	2213	DECENT
1	1	CDL	78933	2210	DECENT
1	1	CR	66094	2435	DECENT
1	1	CR	73457	1309	DECENT

