

06/18

585'

MW 8.6 #/gal      Vis 40                      pH 9.5

WOC. Cut off conductor and casing. Weld on casing head. Test welds to 1500 psi-OK. Install BOPE. Test to 1200 psi-OK. MU bit & BHA. RIH to 495'. Test BOPE to 750 psi-OK. Witnessed and approved by D. Wermiel DOGAMI. Drill out shoe. Drill 7 7/8" hole from 502'-585' @ 6:00 AM.

06/19

1280'

MW 8.8 #/gal      Vis 34                      pH

Circulate and survey @ 585'. Drill from 585'-864'. Drill from 864'-895'. Circulate and survey. Drill from 895'-988'. Circulate clean. POOH. MU new bit, mud motor and BHA. RIH to 988'. Drill w/mud motor to 1000'. Circulate and survey. Drill from 1000'-1062'. Circulate and survey. Drill from 1062'-1124'. Circulate and survey. Drill from 1124'-1186'. Circulate and survey. Drill from 1186'-1217'. Circulate and survey. Drill from 1217'-1280'. Circulate and survey. POOH. Lay down mud motor. MU new BHA. RIH to 1210' @ 6:00 AM.

06/20

2042'

MW 8.7 #/gal      Vis 37                      pH 8.0

Ream from 1210'-1280'. Drill to 1375'. Circulate and survey. Drill from 1375'-1530'. Circulate and survey. POOH. Change BHA. RIH to 1530'. Circulate for loggers. Drill from 1530'-1724'. Circulate and survey. Drill from 1724'-1817'. Circulate and wipe hole to 985'. Circulate for logger. Drill from 1817'-1910'. Circulate and survey. Drill from 1910'-2033'. Circulate and survey. Wipe hole to 672'. Drill from 2033'-2042' @ 6:00 AM.

06/21

2826'

MW 9.3 #/gal      Vis 39                      pH 7.5

Drill from 2042'-2251'. Circulate clean. Wipe hole 5 stds. Circulate and survey. Drill from 2251'-2500'. Circulate and survey. Wipe hole 6 stds. Drill from 2500'-2807'. Circulate and survey. Wipe hole to 2207'. Drill from 2207'-2826' @ 6:00 AM.

06/22

3331' TD

MW 9.4 #/gal      Vis 40                      pH 7.0

Drill from 2826'-2827'. Circulate and POOH. Change bit. RIH to 2827'. Circulate for logger. Drill from 2827'-3024'. Circulate and wipe hole 6 stds. Drill from 3024'-3331' TD @ 4:00 AM 6/22/93. Circulate and survey. POOH for wiper trip to shoe @ 6:00 AM.

06/23

3331' TD

MW 9.4 #/gal      Vis 38                      pH 7.0

POOH for wiper trip. Jars went off with pipe in slips. Pipe fell to