

MISCELLANEOUS NOTICES AND REPORTS ON WELLS AND STRATIGRAPHIC HOLES
(Submit in triplicate)

This is a combined form, use only portions pertinent to your needs.

To comply with rules and regulations adopted pursuant to ORS 520 (Chapter 667 OL 1953).

Notices		Reports	
Indicate nature of notice by checking below:		Indicate nature of report by checking below:	
Notice of intention to plug well	X	Report on plugging well (use form 5)	
Notice of intention to make formation test		Report on making formation test	
Notice of intention to make production test		Report on making production test	
Notice of intention to abandon well		Report on abandoning well	
Notice of intention to test casing shut-off		Report on testing casing shut-off	
Notice of intention to redrill or deepen well		Report on redrilling or deepening well	
Notice of intention to shoot or chemically treat well		Report on shooting or chemically treating well	
Notice of intention to complete well		Report on completion of well	

Submit notices in triplicate before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Department or agent, of the plan submitted.

Submit reports in triplicate within 20 days after the work specified is completed.

St. Helens, Oregon, October 31 1975

Department of Geology and Mineral Industries
Portland, Oregon

Following is a ~~report on the work done and the results obtained~~ notice of intention to do certain work as described below at the Reichhold Energy Corporation Company or Operator
Crown Zellerbach Well No. NNG-CZ No. 2 in NW/4 SW/4 Lease

of sec. 8, T. 4N, R. 3W, W.B. & M., --- field,
Columbia County. The dates of this work were as follows: _____.

Notice of intention to do the work ~~was~~ (was not) submitted on form _____ on _____ 19____ and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

The present condition of the well, including complete casing record, is as follows (Use additional sheets as needed):

1. 9-5/8" surface casing cemented at 565'.
2. 8-3/4" hole drilled to 5805'.
3. No oil or gas shows were found.

FOLLOWING IS A COMPLETE DETAILED ACCOUNT OF ~~WORK DONE AND RESULTS OBTAINED~~ PROPOSED WORK
(USE ADDITIONAL SHEETS AS NEEDED)

1. Hang drill pipe at 615' and pump in 100 sacks of cement.
Your Department will be notified to witness top of plug at or above 515'.
2. Hang drill pipe at 60' and fill surface casing with cement.
3. Cut off surface casing 4' below ground level and weld on steel plate.
4. Clean up location.

Last produced _____ (date) _____ (net oil) _____ (gravity) _____ (cut)

Approved _____ 19____
except as follows:

DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
By _____
Director

REICHHOLD ENERGY CORPORATION
Company or operator
By W.S. [Signature]
Position Engineer
Send communications regarding well to
Name Robert L. Beardsley
Address P. O. Box 810
St. Helens, Oregon