

5. LEASE DESIGNATION AND SERIAL NO. USL-OR-7399

6. IF INDIAN, ALLOTTEE OR TRIBE NAME Not applicable

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [] GAS WELL [] OTHER [] Dry and abandoning

2. NAME OF OPERATOR MICHEL T. HALBOUTY

3. ADDRESS OF OPERATOR 5100 Westheimer, Suite 500, Houston, Texas 77056

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 334' FEL & 2299' FNL, Sec. 10, T-23-S, R-29-E, W.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, GR, etc.) 4761' Gr.

12. COUNTY OR PARISH Harney

13. STATE Oregon

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON* [X] REPAIR WELL [] CHANGE PLANS [] (Other) []

SUBSEQUENT REPORT OF:

- WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT* [X] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plug and Abandon Operations

- *1. Drilling mud of 0.996 specific gravity (8.3#/gal.) in hole at time of P & A. *2. Set 50 sack Class "G" cement plug from 6020' to 5912' *3. Set 200 sack Class "G" cement plug across casing seat @ 2525' from 2600' to 2395' #4. Set 25' cement plug in top of 10-3/4" casing. #5. Cut 10-3/4" casing and 16" conductor off 3-1/2' below ground level. #6. Weld steel plate on top of cut casing and conductor. * Work done subsequent to initial report 9-10-77. Verbal approval received from Mr. John P. Wagner via phone and Mr. Joe DeLozier on the ground. # To be accomplished after State of Oregon runs temperature surveys.

(Over)

18. I hereby certify that the foregoing is true and correct

SIGNED Doyle W. McClennen TITLE General Superintendent DATE 9-16-77

APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

5. LEASE DESIGNATION AND SERIAL NO. USL-OR-7399

6. IF INDIAN, ALLOTTEE OR TRIBE NAME Not applicable

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL [] GAS WELL [] OTHER [] Dry and abandoning

2. NAME OF OPERATOR MICHEL T. HALBOUTY

3. ADDRESS OF OPERATOR 5100 Westheimer, Suite 500, Houston, Texas 77056

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 334' FEL & 2299' FNL, Sec. 10, T-23-S, R-29-E, W.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4761' Gr.

12. COUNTY OR PARISH Harney

13. STATE Oregon

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON* [] REPAIR WELL [] CHANGE PLANS [] (Other) []

SUBSEQUENT REPORT OF:

- WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT* [X] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PLUG & ABANDON OPERATIONS

- 1. Drilling mud of 0.996 specific gravity (8.3#/gal.) in hole at time of P & A. 2. Set 50 sx. Class "G" cement plug from 6020' to 5912'. 3. Set 200 sx. Class "G" cement plug across casing seat @ 2525' from 2600' to 2395' *4. Set 25' cement plug in top of 10-3/4" casing. *5. Cut off 10-3/4" and 16" casing 3-1/2' below ground level. *6. Steel plate welded on top of cut casing, and conductor.

Above procedure approved by Jr. John P. Wagner via telephone and Mr. Joe DeLozier on the ground.

* Operation being performed by State of OREGON.

18. I hereby certify that the foregoing is true and correct

SIGNED Doyle W. McClennen TITLE General Superintendent DATE 8-18-78

APPROVED BY J. Wagner TITLE District Engineer DATE August 21, 1978

cc: BLM District Office, Burns Dist. Office, Burns, Oregon 97720 Dept. of Geology & Minerals Ind., Portland, Oregon 97201

*See Instructions on Reverse Side