

*Received
Feb 21, 1966*

PLUGGING RECORD

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes.

Rule L of rules and regulations adopted pursuant to ORS 520.095 (1) (13) (Chapter 667 OL 1953)

Operator John T. Miller Field Dallas Area
Pool _____
County Polk

ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO: John T. Miller

Street P.O. Box 42 City Hubbard State Oregon

Lease Name Ray Adams Well No. 2 Sec. 11 T. 8 S R. 5 W

Date well was plugged February 15 19 66.

Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? Yes

How was the mud applied? From surface Were plugs used? Yes If so, show all shoulders left for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock.

Use additional sheets if necessary.

8" surface casing cemented at 40 feet with 8 sacks.

3 1/2" tubing set at 617 feet with 4 1/2-foot anchor.

(See attached sheet for plugging details)

Was notice given, before plugging, to all available adjoining lease and land owners?

John T. Miller
(Operator)

AFFIDAVIT

State of Oregon

County of Maxion

I, John T. Miller, being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report.

Subscribed and sworn to before me this 18th day of February 1966.

Notary public in and for Edna Nelson (Oregon)

My commission expires July 11, 1966.