

STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
1069 State Office Building Portland 1, Oregon

HISTORY OF OIL OR GAS WELL

(Submit in duplicate)

RECEIVED-PTLD

DEC 21 1981

In compliance with rules and regulations adopted pursuant to ORS 520.095 (Chapter 667 OL 1953)

DEPT OF GEOLOGY
.....

Operator Reichhold Energy Corp.

Field Mist

Well No. Cadenza 34-1

, Sec. 1

, T. 6N

R. 5W

W. B. & M.

Signed *Tim Williams*

Date 12-8-81

Title Drilling Superintendent

(President, Secretary or Agent)

It is of the greatest importance to have a complete history of the well. Use this form in reporting the history of all important operations at the well, together with the dates thereof, prior to the first production. Include in your report such information as size of hole drilled to cementing or landing depth of casings, number of sacks of cement used in the plugging, number of sacks or number of feet of cement drilled out of casing, depth at which cement plugs started, and depth at which hard cement encountered. If the well was dynamited, give date, size, position and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.

Date	If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.
11- 8-81	Drilling 9 7/8 surface hole
11- 9-81	Finished drilling surface hole to 677'
	Ran 16 JTs 7" 20# K-55 pipe to a total depth of 634.58 as measured
	from a 11.40 Kelly Bushing cemented same with 400 SXs class G cement
11-10-81	Waiting on cement to cure, rig up BOP's & test same, drilling cement &
	shoe, depth 725'
11-11-81	Drilling 6 1/4 hole Depth 1547
11-12-81	" " " " 2114
11-13-81	" " " " 2826
11-14-81	Logging & plugging well
	1st plug 2345' - 2045'
	2nd plug 834' - 534'
11-15-81	Abandoned well