

MISCELLANEOUS NOTICES AND REPORTS ON WELLS AND STRATIGRAPHIC HOLES  
(Submit in triplicate)

This is a combined form, use only portions pertinent to your needs.

To comply with rules and regulations adopted pursuant to ORS 520 (Chapter 667 OL 1953).

Notices		Reports	
Indicate nature of notice by checking below:		Indicate nature of report by checking below:	
Notice of intention to plug well + <u>ABANDON</u>	<input checked="" type="checkbox"/>	Report on plugging well (use form 5)	<input type="checkbox"/>
Notice of intention to make formation test	<input type="checkbox"/>	Report on making formation test	<input type="checkbox"/>
Notice of intention to make production test	<input type="checkbox"/>	Report on making production test	<input type="checkbox"/>
Notice of intention to abandon well	<input type="checkbox"/>	Report on abandoning well	<input type="checkbox"/>
Notice of intention to test casing shut-off	<input type="checkbox"/>	Report on testing casing shut-off	<input type="checkbox"/>
Notice of intention to redrill or deepen well	<input type="checkbox"/>	Report on redrilling or deepening well	<input type="checkbox"/>
Notice of intention to shoot or chemically treat well	<input type="checkbox"/>	Report on shooting or chemically treating well	<input type="checkbox"/>
Notice of intention to complete well	<input type="checkbox"/>	Report on completion of well	<input type="checkbox"/>

Submit notices in triplicate before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Department or agent, of the plan submitted.

Submit reports in triplicate within 20 days after the work specified is completed.

McMinnville, Oregon, September 21 1975

Department of Geology and Mineral Industries  
Portland, Oregon

Following is a report on the work done and the results obtained at the Reichhold Energy Corporation  
notice of intention to do certain work as described below Company or Operator

Finn Well No. NNG-Finn 1 in NW/4 SW/4  
Lease

of sec. 17, T. 6S, R. 4W, W.B. & M., \_\_\_\_\_ field,  
\_\_\_\_\_ County. The dates of this work were as follows: \_\_\_\_\_.

Notice of intention to do the work was (was not) submitted on form \_\_\_\_\_ on \_\_\_\_\_ 19\_\_\_\_  
and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

The present condition of the well, including complete casing record, is as follows (Use additional sheets as needed):

- (a) 9-5/8" surface casing cemented at 652'
- (b) 8-3/4" hole drilled to 7252'
- (c) No oil or gas shows found

FOLLOWING IS A COMPLETE DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED  
(USE ADDITIONAL SHEETS AS NEEDED) PROPOSED WORK

1. Hang drill pipe at 5000' and pump in and equalize 80 sx of cement.
  2. Hang drill pipe at 702' and pump in and equalize 100 sx of cement.
- Your Department will be notified to witness top of plug at or above 602'.
3. Plug surface casing with cement from 60'-18'. Weld on steel plate.
  4. Clean up location.

Last produced \_\_\_\_\_ (date) \_\_\_\_\_ (net oil) \_\_\_\_\_ (gravity) \_\_\_\_\_ (cut)

Approved \_\_\_\_\_ 19\_\_\_\_  
except as follows:  
  
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES  
By \_\_\_\_\_  
Director

Reichhold Energy Corporation  
Company or operator  
By W.S. McBurnie  
Position Engineer  
Send communications regarding well to  
Name Robert L. Beardsley  
Address P.O. Box 810  
St. Helens, Oregon 97051