

RECEIVED - PTLD

JAN 25 1985

PLUGGING RECORD

DEPT. OF GEOLOGY  
& MINERAL INDUSTRIES

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes.

Rule L of rules and regulations adopted pursuant to ORS 520.095 (1) (13) (Chapter 667 OL 1953)

Operator Reichhold Energy Corporation Field Mist  
Pool \_\_\_\_\_  
County Columbia

ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO:

Street 12655 SW Ctr., Suite 240 City Beaverton, State Oregon

Lease Name Longview Fibre Well No. 42-22 Sec. 22 T. 6N R. 5W

Date well was plugged January 17, 1985.

Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? Yes

How was the mud applied? pumped Were plugs used? Yes If so, show all shoulders left for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock.

Use additional sheets if necessary.

8 5/8" casing set @ 436.10'  
Bottom plug set @ 1650' - 1540' with 32 sx Class "G" 2% CaCl cement  
Top plug set @ 498' - 311' with 68 sx class "G" 2% CaCl cement  
10 ft surface plug

Was notice given, before plugging, to all available adjoining lease and land owners? Yes

Reichhold Energy Corporation  
(Operator)

AFFIDAVIT

State of Oregon

County of Columbia

I, [Signature], being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report.

Subscribed and sworn to before me this 22nd day of January 1985

Notary public in and for (State of Oregon) [Signature]  
Mary A. Hawkes

My commission expires 2-13-88