

DAMON PETROLEUM

WELL Stauffer Farms 35-1

DEPTH START 2752'

TOUR Days

DEPTH END Clean ou to 1300'

DATE 9/10/87

CONTRACTOR Jannsen Drilling

HOUR	WORK DESCRIPTION
9:30A	Prepare to place abandonment plug.
	CEMENT PLUG 380'-270'
	Began pumping in 35 sacks of ready mix cement thru
	2 7/8' open end drill pipe. Cement in place at 12:30PM
	Pull drill pipe up to a depth of 200' and circulate
	out excess cement.
5:30P	Run in with 6½" bit on 2 7/8" drill pipe. Found top
	of firm cement at 270'. State approved the abandon-

DETAIL OF OPERATIONS ment plug (Dan Wermiel, State Inspector).

Begin moving out drilling equipment and mud tanks.

Charge 6 Hours of drilling time.

MUD WT _____ MUD VISC. _____

CIRCULATING PUMP PRESSURE _____

ROTARY SPEED _____ BIT# _____ DEPTH IN _____ DEPTH OUT _____

DRILLER Preston Jannsen

CREW Dave ?