

INSPECTION RECORD

DISTRICT Santa Rosa (Forest Service Permit - Detroit R.D.)

AREA Breitenbush Hot Springs DATE 8/31/78

COMPANY Sunoco Energy Devel. Co. DRILLING CONTRACTOR Skyles Drlg. Co.

~~LEASE NO.~~ Pre-Lease WELL NO. Breitenbush #1

LOCATION SE 1/4 NE 1/4 Sec 14, COUNTY Marion STATE Oregon
T9S, R8E, WM

WELL ABANDONMENT

CASING: 145' of 7 5/8" pipe set with 5 cu. yds.
construction cement. Returns to the
surface. Set 2" tubing to T.D. with
top 145' cemented.



TOTAL DEPTH: 1190' (4 3/4" hole)

PLUGGING OPERATIONS: Cut tubing and casing 2-3' below surface and cemented
top 10' of tubing with construction cement.

SITE RESTORATION: Pit and hole filled and resloped to original contour.

REMARKS: Area restored in a satisfactory manner.

INSPECTOR: [Signature] SECTION: Dist. Geoth. Supervisor

INSPECTION TIME: 4 hrs. (Travel included)