

## REICHHOLD ENERGY CORPORATION

CROWN ZELLERBACH NO. 4

Section 36-5N-4W, W.B. &amp; M.

Columbia County, Oregon

Side Wall Sample Descriptions

Described by: Mr. Wes Bruer

<u>DEPTH</u>	<u>RECOVERY</u>	<u>DESCRIPTION</u>
5,987'	0"	No Recovery
5,981'	0"	No Recovery
5,984'	0"	Miss-fire
5,986'	0"	No Recovery
5,987'	1/2"	Sand, same as 6,042' but somewhat more kaolinitic. No odor or visible stain, but spotty whitish fluorescence and very faint yellowish cut.
5,990'	0"	No Recovery
6,006'	0"	Shot off
6,021'	0"	No Recovery
6,024'	0"	No Recovery
6,027'	0"	No Recovery
6,030'	1/2"	Sand, same as 6,042'. No odor, stain, cut or fluorescence.
6,037'	0"	No Recovery
6,042'	1/2"	Sand, light gray, easily friable, fine to scarcely medium, salt and pepper appearance, somewhat silty and kaolinitic. Probably low permeability. Faint pungent odor, no visible staining, fluorescence, or cut.
6,053'	1-1/4"	Sand, same as 6,055' but locally firm. Includes 1/4" firm dark gray sandy siltstone. Faint sweet odor. Occasional spots with light brown staining, stains fluorescence dull salmon-orange. Trichlorethane cut fluorescences milky white.
6,055	1-1/4"	Sand, Med. gray, easily friable, V.fine to fine, very silty. Prob. very low permeability. No odor, stain, cut or fluorescence.