

# Corvallis Fire Station #4

Bent\_fir05A

City of Corvallis

Building Type	County	
Fire - City	Benton	
Street		
365 SW Tunison		
City	State	Zip
Corvallis	OR	97333
Latitude	Longitude	
44.54357	123.26912	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Corvallis Fire Station #4

## Final RVS Score

Final Type      Final Score

W1

3.8

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Plan Irregularity Primary



NE Vertical Irregularity Primary