

Metolius Elementary School

Jeff_sch09A

Jefferson County SD 509J

Building Type	County	
School	Jefferson	
Street		
420 Butte Ave Sw		
City	State	Zip
Madras	OR	97741
Latitude		Longitude
44.58736		121.17197
Tracking Code		Inspection Date
RVS in 2006		8/9/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Metolius Elementary School

Final RVS Score

Final Type Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
237		1949	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31080	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	Steps in Elevation View: Single Change
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Elevation View



W Elevation View

Metolius Elementary School

Jeff_sch09B

Jefferson County SD 509J

Building Type	County	
School	Jefferson	
Street		
420 Butte Ave Sw		
City	State	Zip
Madras	OR	97741
Latitude		Longitude
44.58778		121.17196
Tracking Code		Inspection Date
RVS in 2006		8/9/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Metolius Elementary School

Final RVS Score

Final Type Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
237		1949	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31080	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
Reentrant Corners: U shaped	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View



E Elevation View



S Elevation View
2000' s addition