

Crescent RFPD

Building Type	County	
Fire - RFPD	Klamath	
Street		
20400 Crescent Lake Hwy		
City	State	Zip
Crescent Lake	OR	97425
Latitude		Longitude
43.52689		121.94863
Tracking Code		Inspection Date
RVS in 2006		7/3/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Secondary	W2	4.8	-3	0	0	1.6	-0.8	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Crescent-Odell Lakes RFPD

Final RVS Score

Final Type      Final Score

W2

2.6

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE General Site

Crescent RFPD

Building Type	County	
Fire - RFPD	Klamath	
Street		
20400 Crescent Lake Hwy		
City	State	Zip
Crescent Lake	OR	97425
Latitude		Longitude
43.52651		121.94837
Tracking Code		Inspection Date
RVS in 2006		7/3/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crescent-Odell Lakes RFPD

Final RVS Score

Final Type      Final Score

W2

3.4

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None