

# Lake Creek Fire & Rescue - Station 1

Lane\_fir32A

Lake Creek RFPD

Building Type	County	
Fire - RFPD	Lane	
Street		
20451 Hwy 36		
City	State	Zip
Blachly	OR	97412
Latitude		Longitude
44.195		123.53459
Tracking Code		Inspection Date
RVS in 2006		8/3/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lake Creek Fire & Rescue - Station 1

## Final RVS Score

Final Type

Final Score

S3

2.8

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW General Site  
Also shows minor plan irregularity.