

# Joseph Elementary School

Wall\_sch07A

Joseph SD 6

Building Type	County	
School	Wallowa	
Street		
201 E 2nd St.		
City	State	Zip
Joseph	OR	97846
Latitude		Longitude
45.3509		117.22754
Tracking Code		Inspection Date
RVS in 2006		8/12/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary	W2	4.8	0	-0.5	0	0	0	-1.2	0	3.1

Joseph Elementary School

## Final RVS Score

Final Type      Final Score

RM1

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
85		1940	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13900	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



W Elevation View