


|               |                 |       |
|---------------|-----------------|-------|
| Building Type | County          |       |
| Fire - RFPD   | Wasco           |       |
| Street        |                 |       |
| 525 Wasco Dr  |                 |       |
| City          | State           | Zip   |
| The Dalles    | OR              | 97058 |
| Latitude      | Longitude       |       |
| 45.59893      | 121.13542       |       |
| Tracking Code | Inspection Date |       |
| RVS in 2006   | 8/23/2006       |       |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | S3   | 3.8         | 0          | -0.5       | 0        | 0          | -0.6   | 0      | 0      | 2.7       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Mid-Columbia Fire & Rescue

Final RVS Score

Final Type      Final Score

S3

2.7

FEMA-154 Collapse Potential

Low (<1%)



|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        |                             |                          | 1990               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
|                        | 1                           | No                       | No                 |

|                              |                         |
|------------------------------|-------------------------|
| Plan Irregularities          | Vertical Irregularities |
| Torsion: Eccentric Stiffness | None                    |
| None                         | None                    |
| None                         | None                    |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



SW Elevation View



W Elevation View



SE Building Name



E Elevation View